

FIG. 1




FIG. 2

[1]	[2]	[3]	[4]
-1	-1	-1	-1
3	-1	1	-1
3	3	8	1
-1	3	8	8
	-1	1	8
		-1	1
			-1

FIG. 3




FIG. 4

	FIRST-ORDER C1	SECOND-ORDER C2	FOURTH-ORDER C3
R1	-0.031		
R2	0		
R3	0.281	0.001	
R4	0.5	0	
R5	0.281	-0.018	
R6	0	-0.031	
R7	-0.031	0.062	0
R8		0.281	0
R9		0.41	0
R10		0.281	0
R11		0.062	0
R12		-0.031	0.002
R13		-0.018	0
R14		0	-0.013
R15		0.001	-0.028
R16			-0.001
R17			0.109
R18			0.263
R19			0.337
R20			0.263
R21			0.109
R22			-0.001
R23			-0.028
R24			-0.013
R25			0
R26			0.002
R27			0
R28			0
R29			0
R30			0
R31			0

FIG. 5







FIG. 6




F I G. 7



F I G. 8




F I G. 9




F I G. 10

LPF1 (4)		HPF1 (4)
0.002	-0.002=	+0.002
0		0
-0.013		0.013
-0.028		0.028
-0.001		0.001
0.109		-0.109
0.263		-0.263
0.337	1-0.337=	0.663
0.263		-0.263
0.109		-0.109
-0.001		0.001
-0.028		0.028
-0.013		0.013
0		0
0.002		-0.002


F I G. 11




F I G. 12



F I G. 13




F I G. 14




F I G. 15

COMBINED FACTOR	TRANSFER FACTOR
-0.001	0.001
0.001	-0.001
-0.001	0.001
0.001	-0.001
0	0
-0.002	0.002
0.005	-0.005
-0.008	0.008
0.011	-0.011
-0.012	0.012
0.01	-0.01
-0.004	0.004
-0.008	0.008
0.025	-0.025
-0.046	0.046
0.07	-0.07
-0.094	0.094
0.113	-0.113
-0.127	0.127
0.131	0.869
-0.127	0.127
0.113	-0.113
-0.094	0.094
0.07	-0.07
-0.046	0.046
0.025	-0.025
-0.008	0.008
-0.004	0.004
0.01	-0.01
-0.012	0.012
0.011	-0.011
-0.008	0.008
0.005	-0.005
-0.002	0.002
0	0
0.001	-0.001
-0.001	0.001
0.001	-0.001
-0.001	0.001


F I G. 16




F I G. 17



F I G. 18A



F I G. 18B



F I G. 18C

